

MERCEDES GLC COUPE GLC 300 D 4MATIC 0432 LVB



218,268.00 Km



25/11/2021



245 BHP



DIESEL



AUTOMATIC



168 g/km



DESCRIPCIÓN ADICIONAL

DIRECT TO MOTORCADE CARS SL FROM AYVENS LEASING

Contacte con nosotros

Motorcade Cars, S.L.
Km 2.2 Camino Viejo De Coin Mijas 29649
665 960 064 + Whatts-app
motorcadespain@gmail.com
www.motorcadespain.com

PRICE
€39995,00

Extra Accessories:

AMG Line

Ambient lighting

50.8 cm (20") AMG light-alloy wheels

Driving Assistance

Package Night

Package Premium Package Plus (without 897 and 810)

Aluminium-look running boards with studs in

MANUFAKTUR diamond white bright paintwork

Instrument cluster display

Works hop Entry Date	Works hop Release	Supplier	Detail	Number of kilometers	Tires Changed
06/03/ 2025	06/03/ 2025	OFFICES - EUROMA	Repair puncture	205,98	0
05/02/ 2025	06/02/ 2025	VALDIMO TOR AUTOMO CION SL	Check / Top up levels Replace antifreeze Renew brake fluid Check / Top up levels Periodic check Replace pollen filter Replace oil Replace oil filter Repair on rear brake system Replace rear brake pads Repair on front brake system Replace front brake pads Repair oil sump Replace pollen filter Cost of labor Mechanics Replace front brake pads Cost of labor Mechanics Repairs on	201,18	
04/12/ 2024	04/12/ 2024	OFFICES - EUROMA	Repair puncture	192,12	0
05/16/ 2024	05/16/ 2024	VALDISA	Replace oil filter Replace oil Amount Labor Mechanics Periodic review Waste rate Repair oil pan Check / Fill	174,51	
03/01/ 2024	04/01/ 2024	MOBILIT Y- CENTER	Replace fuel filter Replace air filter Replace air filter Replace pollen filter Replace pollen filter Periodic inspection Replace oil filter Replace oil Amount Labor Mechanics Replace air filter Repair on central locking Replace pollen filter Replace fuel filter Replace front wiper blades Replace brake fluid Periodic inspection Repairs on steering system Amount Labor Mechanics Replace rear brake pads Replace pollen filter Waste fee	149,00	
11/30/ 2023	11/30/ 2023	PIRELLI TIRES	See observations	143,88	0
01/08/ 2023	01/08/ 2023	*CITYCA R SUR SA	Small Material Inspection 125000 km. Replace oil Replace oil filter Replace pollen filter Renew/Replace oil Repair oil sump Renew/Replace oil Check/Refill levels Amount Labor Mechanics Replace pollen filter Renew/	125,80	
04/27/ 2023	04/27/ 2023	PIRELLI TIRES	Repair puncture	110,01	0
04/27/ 2023	04/27/ 2023	*CITYCA R SUR SA	Small Material Replacing front brake discs Replacing front brake discs Repair on front brake system Replacing front brake pads Amount Labor Mechanics	110,02	
04/24/ 2023	04/24/ 2023	PIRELLI TIRES	See observations	10,800	0
06/03/ 2023	06/03/ 2023	*CITYCA R SUR SA	100,000 km inspection. Replace pollen filter. Replace oil filter. Replace oil. Replace pollen filter. Repair on central locking. Check/fill levels. Replace front windscreen wiper blades. Amount. Labor. Mechanics. Replace front windscreen wiper blades. Check/fill levels. Central	100,02	

10/19/ 2022	10/19/ 2022	OFFICES - EUROMA	Repair puncture	74.435	0
04/10/ 2022	05/10/ 2022	*CITYCA R SUR SA	Replace air filter Replace air filter Replace oil Replace oil filter Replace fuel filter Repair on front brake system Replace rear brake pads Repair on rear brake system Check / Fill levels Small Material Amount Labor Mechanics Repair on front brake system Repairs on steering system Body repairs Amount Labor Mechanics	72.265	
June 14, 2022	June 14, 2022	OFFICES - EUROMA	See observations	49.349	2
06/13/ 2022	06/13/ 2022	*CITYCA R SUR SA	Check / Fill levels Amount Labor Mechanics Periodic review Check / Fill levels Replace pollen filter Check / Fill levels Periodic review Replace oil Repair oil pan	47,500	
June 14, 2022	June 14, 2022	OFFICES - EUROMA	See observations	49.349	0
03/25/ 2022	03/25/ 2022	*CITYCA R SUR SA	Check / Top up levels 25,000km inspection. Repair oil sump. Replace pollen filter. Replace oil filter. Replace oil. Amount of labor. Mechanics. 25,000km inspection.		

Extra Accessories:

AMG Line

Ambient lighting

50.8 cm (20") AMG light-alloy wheels

Driving Assistance

Package Night

Package Premium Package Plus (without 897 and 810)

Aluminium-look running boards with studs in

MANUFAKTUR diamond white bright paintwork

Instrument cluster display