

FORD PUMA 1.0 ECOBOOST 92KW (125CV) TITANIUM MHEV 6634 LLT



238,622.00 Km



21/12/2020



125 DIN



PETROL



MANUAL



97 g/km



OPTIONS

Extra Accessories:

Black roof bars

Solid white

Privacy glass

Comfort package

Solid paint

Black fabric

Total options price : 843.00 €

DESCRIPCIÓN ADICIONAL

DIRECT FROM ALD AUTOMOTIVE TO MOTORCADE CARS SL

Contacte con nosotros

Motorcade Cars, S.L.

Km 2.2 Camino Viejo De Coin Mijas 29649

665 960 064 + Whatts-app

motorcadespain@gmail.com

www.motorcadespain.com

PRICE
€12995

6634 LLT 21/12/2020

Extra Accessories:

Black roof bars

Solid white

Privacy glass

Comfort package

Solid paint

Black fabric

Works hop Entry Date	Works hop Release	Supplier	Detail	Number of kilometers	Tires Changed
04/22/ 2025	04/23/ 2025	LAMSAUTO	Amount of labor, mechanics, diagnosis	235,34	
04/10/ 2024	04/10/ 2024	AUTOELE CTRIC PUJOL,	Cost Management Authorization Check / Fill levels Waste rate Repair oil pan Check / Fill levels Replace oil filter Replace pollen filter	207,78	
11/06/ 2024	11/06/ 2024	OFFICES - EUROMA	Prick	190.12	
04/18/ 2024	04/18/ 2024	Rodi Cervera	Forwards	182.22	2
10/04/ 2024	10/04/ 2024	AUTOELE CTRIC PUJOL, SL	Inspection 180,000 km. Replace oil filter Replace air filter Replace spark plugs Replace oil Cost Management Authorization Inspection 180,000 km. Replace oil Replace air filter Replace spark plugs Replace pollen filter	179.17	
02/11/ 2023	03/11/ 2023	AUTOELE CTRIC PUJOL, SL	150,000 km inspection. Replace oil filter. Replace pollen filter. Replace oil. Cost: Authorization. 150,000 km inspection. Replace oil. Replace pollen filter. Replace antifreeze.	149,54	
06/09/ 2023	06/09/ 2023	Rodi Cervera	Forwards	123.06	3
05/26/ 2023	05/26/ 2023	Celesti Farre Workshop s	Cost of Authorization Management Inspection 120,000 km. Replace pollen filter Replace oil Replace oil filter Replace air filter Replace spark plugs Accessory belt Inspection 120,000 km. Replace oil Replace spark plugs Replace pollen filter Accessory belt Replace air filter Accessory belt Inspection 120,000 km.	119,52	
10/27/ 2022	10/27/ 2022	AUTOELE CTRIC PUJOL, SL	Cost of Authorization Management Inspection 90,000 km. Replace oil filter Replace pollen filter Replace oil Inspection 90,000 km. Replace pollen filter Replace oil Check / Top up	88,917	
04/20/ 2022	04/20/ 2022	Rodi Cervera	Rear	60,024	3

FORD PUMA 1.0

EcoBoost 125 BHP

Titanium MHEV

04/19/ 2022	04/19/ 2022	AUTOELE CTRIC PUJOL, SL	Cost of Authorization Management Inspection 60,000 km. Replace oil filter Replace air filter Replace spark plugs Replace pollen filter Replace oil Cost of Authorization Management Inspection 60,000 km. Replace air filter Replace spark plugs Replace pollen filter	59,945	
12/11/ 2021	12/11/ 2021	BRIDGES TONE (OFFICE	Prick	31.179	
02/11/ 2021	02/11/ 2021	AUTOELE CTRIC PUJOL, SL	Cost of Authorization Management Inspection 30,000 km. Replace oil filter Replace pollen filter Replace oil Inspection 30,000 km. Replace pollen filter Replace oil Check / Top up	30,081	

Extra Accessories:

Black roof bars

Solid white

Privacy glass

Comfort package

Solid paint

Black fabric